

Inspection Report

Permit Holder: Canadian Natural Resources Limited
Inspection: 2026-1567
Inspection Date: 2026-05-14
Inspection Outcome: Inspected

Inspection Comment:

Inspect access and access signage.

Pad clean and moderately vegetated.

Wellhead is the only equipment on site. Barricaded. Fully suspended. Wing valve is not included in lockout cable. SCV has PSV and pressure build-up testing equipment installed.

Associated pipeline well vegetated.

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100067483
Well ID: 25086
Well Name: CNRL SUNDOWN C- 036-L/093-P-08
Location: NTS: C- 036-L/093-P-08

Permit: 100107527
Road Number: 05252
Segment IDs (Location): 002 (From NTS: D- 036-L/093-P-08 To NTS: C- 036-L/093-P-08)

Authorized by BCER