

Inspection Report

Permit Holder: Ovintiv Canada ULC
Inspection: 2026-1574
Inspection Date: 2026-05-13
Inspection Outcome: Inspected

Inspection Comment:

Access road good, signage is present and lease is free of debris. ESD(s) and scv(s) at wellhead meet current regulations. Chem Tank(s) DW meets current regulations.

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100053092
Well ID: 20998
Well Name: OVV ECOG HZ CUTBANK B- 013-B/093-P-08
Location: NTS: B- 013-B/093-P-08

Permit: 100053092
Facility ID: 00022019
Facility Name: OVV DEEPBASIN B-013-B/093-P-08 001
Facility Type: Well Facility
Location: NTS: B- 013-B/093-P-08

Authorized by BCER