

Inspection Report

Permit Holder: Ovintiv Canada ULC
Inspection: 2026-1575
Inspection Date: 2026-05-14
Inspection Outcome: Inspected

Inspection Comment:

Access low grade/winter road. Drove part way and walked part way.

Access signage clear and legible.

Inspect well and well building. No SCV flow observed. No signage on well building.

** Chemical tanks secondary containment is partially damaged, water in the containment. Please ensure the containment is capable of holding the contents of the tank.

Associated pipeline well vegetated.

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100040700
Well ID: 17237
Well Name: OVV ET AL SUNDOWN A- 065-I/093-P-07
Location: NTS: A- 065-I/093-P-07

Permit: 100070307
Road Number: 01359
Segment IDs (Location): 003 (From NTS: B- 074-I/093-P-07 To NTS: D- 065-I/093-P-07)

Authorized by BCER