

Inspection Report

Permit Holder: Ovintiv Canada ULC
Inspection: 2026-1576
Inspection Date: 2026-05-14
Inspection Outcome: Inspected

Inspection Comment:

Inspect access and access signage.

Pad clean.

Inspect wells. A well has burst plate installed on SCV. 0 well no SCV flow observed. Meter inspected. Signage clear and legible. Wellheads barricaded.

Associated pipeline well vegetated.

A satisfactory inspection was conducted.

The following were the only items that were inspected during this inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this inspection.

Permit: 100055655
Well ID: 21591
Well Name: OVV ECOG ET AL HZ SUNDOWN B- 051-I/093-P-07
Location: NTS: B- 051-I/093-P-07

Permit: 100055656
Well ID: 21592
Well Name: OVV ECOG ET AL HZ SUNDOWN B-A051-I/093-P-07
Location: NTS: B-A051-I/093-P-07

Permit: 100055655
Facility ID: 00022296
Facility Name: OVV DEEPBASIN B-051-I/093-P-07 001
Facility Type: Well Facility
Location: NTS: B- 051-I/093-P-07

Authorized by BCER