

Inspection Report

Permit Holder: Ovintiv Canada ULC
Inspection: 2026-1579
Inspection Date: 2026-05-13
Inspection Outcome: Inspected

Inspection Comment:

Access road good, signage is present and lease is free of debris. ESD(s) and scv(s) at wellhead meet current regulations. Chem Tank(s) and secondary containment and pigging station(s) meet current regulations.

Well identifier sign at lease entrance is laying on the ground

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100039923
Well ID: 16835
Well Name: OVV ECOG HZ CUTBANK C- 003-B/093-P-08
Location: NTS: C- 003-B/093-P-08

Permit: 100039923
Facility ID: 00020425
Facility Name: OVV DEEPBASIN C-003-B/093-P-08 001
Facility Type: Well Facility
Location: NTS: C- 003-B/093-P-08

Authorized by BCER