

## Inspection Report

Permit Holder: ConocoPhillips Canada Resources Corp.  
Inspection: 2026-1582  
Inspection Date: 2026-05-13  
Inspection Outcome: Inspected

### Inspection Comment:

For Information Only:

Both wellhead valves are secured. Cement barricade around wellheads.

All flowlines and equipment have been removed.

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100058686  
Well ID: 22558  
Well Name: COP HZ FIREWEED D- 076-I/094-A-12  
Location: NTS: D- 076-I/094-A-12

Permit: 100068517  
Well ID: 25221  
Well Name: COP HZ FIREWEED D-A076-I/094-A-12  
Location: NTS: D-A076-I/094-A-12

Permit: 100058686  
Facility ID: 00022712  
Facility Name: COP FIREWEED D-076-I/094-A-12 001  
Facility Type: Well Facility  
Location: NTS: D- 076-I/094-A-12

Permit: 100068517  
Facility ID: 00024054  
Facility Name: COP FIREWEED D-076-I/094-A-12 003  
Facility Type: Well Facility  
Location: NTS: D- 076-I/094-A-12

---

Authorized by BCER



Inspection Number: 2026-1582  
Inspection Date: 2026-05-13

Letter ID: L2602255  
Letter Date: 2026-05-15