

## Inspection Report

Permit Holder: Canadian Natural Resources Limited  
Inspection: 2026-1584  
Inspection Date: 2026-05-13  
Inspection Outcome: Non-Compliance(s) Found

### Inspection Comment:

Access road good, signage is present and lease is free of debris. ESD(s) and scv(s) at wellhead meet current regulations. Chem Tank(s) and secondary containment and pigging station(s) meet current regulations.

An Inspection was conducted and as a result Non-Compliance(s) were found and must be corrected. For specifics on the Non-Compliances, refer to the **Non-Compliance Notice**.

To respond to these Non-Compliances, access the CM-IS Permit Holder Application.

Consideration should be given to checking your other locations for similar Non-Compliances.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100027612  
Well ID: 13117  
Well Name: CNRL NOEL C- 076-J/093-P-01  
Location: NTS: C- 076-J/093-P-01

Permit: 100054368  
Well ID: 21244  
Well Name: CNRL HZ NOEL B- 076-J/093-P-01  
Location: NTS: B- 076-J/093-P-01

Permit: 100027612  
Facility ID: 00019635  
Facility Name: CNRL NOEL C-076-J/093-P-01 001  
Facility Type: Well Facility  
Location: NTS: C- 076-J/093-P-01

Permit: 100033818  
Facility ID: 00007174  
Facility Name: CNRL NOEL C-076-J/093-P-01 002  
Facility Type: Compressor Station  
Location: NTS: C- 076-J/093-P-01

Permit: 100054368  
Facility ID: 00022128  
Facility Name: CNRL DEEPBASIN B-076-J/093-P-01 001  
Facility Type: Well Facility  
Location: NTS: B- 076-J/093-P-01

---

Authorized by BCER