

## Inspection Report

Permit Holder: R360 Environmental Solutions Canada Inc.  
Inspection: 2026-1585  
Inspection Date: 2026-05-14  
Inspection Outcome: Inspected

### Inspection Comment:

Risk & Data Informed inspection of surface equipment on site.

Performed inspection of location at 1455HRS.

Access road- No concerns at the time of inspection.

Lease environment- No erosion sediment or water runoff concerns.

Lease Equipment: Wellhead Suspended & located inside beehive building. Building entry test- No alarms on personal monitor. Signage in place. Positive isolation maintained (flow lines removed). Valve Handles chained, locked and secure.

Surface casing vent flow test- No Flow detected from glove test.

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100075720  
Well ID: 28116  
Well Name: R360 CANADA HZ W STODDART A10-30-087-20  
Location: DLS: A10-30-087-20

---

Authorized by BCER