

## Inspection Report

Permit Holder: ConocoPhillips Canada Resources Corp.  
Inspection: 2026-1586  
Inspection Date: 2026-05-13  
Inspection Outcome: Inspected

### Inspection Comment:

For Information Only:

Both wellhead valves are secured. Cement barricades around both wellheads.

All flowlines and equipment have been removed.

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100079439  
Well ID: 29899  
Well Name: COP HZ FIREWEED A- 065-I/094-A-12  
Location: NTS: A- 065-I/094-A-12

Permit: 100080427  
Well ID: 30463  
Well Name: COP HZ FIREWEED A-A065-I/094-A-12  
Location: NTS: A-A065-I/094-A-12

Permit: 100079439  
Facility ID: 00018096  
Facility Name: COP FIREWEED A-065-I/094-A-12 001  
Facility Type: Well Facility  
Location: NTS: A- 065-I/094-A-12

---

Authorized by BCER