

Inspection Report

Permit Holder: Canadian Natural Resources Limited
Inspection: 2026-1587
Inspection Date: 2026-05-13
Inspection Outcome: Inspected

Inspection Comment:

Access road good, signage is present and lease is free of debris. ESD(s) and scv(s) at wellhead meet current regulations. Chem Tank(s) and secondary containment and pigging station(s) meet current regulations.

Culvert that appears to be garbage in the ditch on lease access rd needs to be addressed.

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100030850
Well ID: 14198
Well Name: CNRL NOEL B- 008-B/093-P-08
Location: NTS: B- 008-B/093-P-08

Permit: 100030850
Facility ID: 00019815
Facility Name: CNRL NOEL B-008-B/093-P-08 001
Facility Type: Well Facility
Location: NTS: B- 008-B/093-P-08

Authorized by BCER