

## Inspection Report

Permit Holder: Canadian Natural Resources Limited  
Inspection: 2026-1591  
Inspection Date: 2026-05-13  
Inspection Outcome: Inspected

### Inspection Comment:

Access road good, signage is present and lease is free of debris. ESD(s) and scv(s) at wellhead meet current regulations. Chem Tank(s) and secondary containment and pigging station(s) meet current regulations.

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100061934  
Well ID: 23424  
Well Name: CNRL HZ CUTBANK C- 084-J/093-P-01  
Location: NTS: C- 084-J/093-P-01

Permit: 100061935  
Well ID: 23427  
Well Name: CNRL HZ CUTBANK C-A084-J/093-P-01  
Location: NTS: C-A084-J/093-P-01

Permit: 100061936  
Well ID: 23428  
Well Name: CNRL HZ CUTBANK C-B084-J/093-P-01  
Location: NTS: C-B084-J/093-P-01

Permit: 100061934  
Facility ID: 00023118  
Facility Name: CNRL DEEPBASIN C-084-J/093-P-01 001  
Facility Type: Well Facility  
Location: NTS: C- 084-J/093-P-01

Permit: 100061935  
Facility ID: 00023120  
Facility Name: CNRL DEEPBASIN C-084-J/093-P-01 002  
Facility Type: Well Facility  
Location: NTS: C- 084-J/093-P-01

Permit: 100061936  
Facility ID: 00023121  
Facility Name: CNRL DEEPBASIN C-084-J/093-P-01 003  
Facility Type: Well Facility  
Location: NTS: C- 084-J/093-P-01

---

Authorized by BCER