

## Inspection Report

Permit Holder: Canadian Natural Resources Limited  
Inspection: 2026-1592  
Inspection Date: 2026-05-13  
Inspection Outcome: Inspected

### Inspection Comment:

Access road good, signage is present and lease is free of debris. ESD(s) and scv(s) at wellhead meet current regulations. Chem Tank(s) and secondary containment and pigging station(s) meet current regulations.

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100073374  
Well ID: 27140  
Well Name: CNRL HZ KELLY C- 074-J/093-P-01  
Location: NTS: C- 074-J/093-P-01

Permit: 100073374  
Facility ID: 00025019  
Facility Name: CNRL CUTBANK C-074-J/093-P-01 001  
Facility Type: Well Facility  
Location: NTS: C- 074-J/093-P-01

---

Authorized by BCER