

Inspection Report

Permit Holder: Shell Canada Limited
Inspection: 2026-1600
Inspection Date: 2026-05-13
Inspection Outcome: Inspected

Inspection Comment:

11-7-79-18

Signage no concerns.

SCV no venting observed.

Metering cabinet no concerns.

Shutdown isolation valve carsealed.

Hydraulic actuator no concerns.

Chemical tank with secondary containment no concerns.

Chemical injection system no concerns.

Propane tank bonded to ground.

Sirius chemical injection system no concerns.

All plugs and caps in place.

No concerns identified at time of inspection.

A11-7-79-18

Signage no concerns.

SCV no venting observed.

Metering cabinet no concerns.

Shutdown isolation valve carsealed.

Hydraulic actuator no concerns.

Chemical tank with secondary containment no concerns.

Chemical injection system no concerns.

Propane tank bonded to ground.

Pigging area no concerns.

All plugs and caps in place.

No concerns identified at time of inspection.

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100065344
Well ID: 24414
Well Name: SHELL HZ HERITAGE 11-07-079-18
Location: DLS: 11-07-079-18

Permit: 100065345
Well ID: 24422
Well Name: SHELL HZ HERITAGE A11-07-079-18
Location: DLS: A11-07-079-18

Permit: 100065344
Facility ID: 00023675
Facility Name: SHELL HERITAGE 11-07-079-18 001
Facility Type: Well Facility
Location: DLS: 11-07-079-18

Permit: 100065345
Facility ID: 00023679
Facility Name: SHELL HERITAGE 11-07-079-18 002
Facility Type: Well Facility
Location: DLS: 11-07-079-18

Authorized by BCER