

Inspection Report

Permit Holder: Shell Canada Limited
Inspection: 2026-1601
Inspection Date: 2026-05-14
Inspection Outcome: Inspected

Inspection Comment:

7-28-79-20

Signage okay.

Metering cabinet no concerns.

Chemical injection system no concerns.

Isolation shutdown valve locked open.

Actuator no concerns.

All plugs and caps in place.

No concerns identified at time of inspection.

A7-28-79-20

Signage okay.

Metering cabinet no concerns.

Chemical injection system no concerns.

Isolation shutdown valve locked open.

Actuator no concerns.

All plugs and caps in place.

No concerns identified at time of inspection.

B7-28-79-20

Signage okay.

Metering cabinet no concerns.

Chemical injection system no concerns.

Isolation shutdown valve locked open.

Actuator no concerns.

All plugs and caps in place.

No concerns identified at time of inspection.

C7-28-79-20

Signage okay.

Wellhead isolated for equipment, chained and locked.

Metering cabinet no concerns.

Chemical injection system no concerns.

Isolation shutdown valve locked open.

Actuator no concerns.

All plugs and caps in place.

No concerns identified at time of inspection.

D7-28-79-20

Signage okay.

Metering cabinet no concerns.

Chemical injection system no concerns.

Isolation shutdown valve locked open.

Actuator no concerns.

All plugs and caps in place.

No concerns identified at time of inspection.

Separator building with secondary containment under construction.

Sirus chemical injection system no concerns.

RTU building no concerns.

3 propane tanks bonded to ground.

E7-28-79-20

Signage okay.

Metering cabinet no concerns.

Isolation shutdown valve locked open.

Actuator no concerns.

Desander no concerns.

All plugs and caps in place.

No concerns identified at time of inspection.

F7-28-79-20

Signage okay.

Metering cabinet no concerns.

Isolation shutdown valve locked open.

Actuator no concerns.

Desander no concerns.

All plugs and caps in place.

No concerns identified at time of inspection.

G7-28-79-20

Signage okay.

Metering cabinet no concerns.

Isolation shutdown valve locked open.

Actuator no concerns.

Desander no concerns.

All plugs and caps in place.

No concerns identified at time of inspection.

Chemical tank with secondary containment no concerns.

Chemical injection system no concerns.

RTU building no concerns.

Separator skid no concerns.

Pigging area no concerns.

Sirius chemical injection system no concerns.

All plugs and caps in place.

No other concerns identified at time of inspection.

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100069248
Well ID: 25644
Well Name: SHELL HZ GROUNDBIRCH A07-28-079-20
Location: DLS: A07-28-079-20

Permit: 100069249
Well ID: 25645
Well Name: SHELL HZ GROUNDBIRCH B07-28-079-20
Location: DLS: B07-28-079-20

Permit: 100069250
Well ID: 25646
Well Name: SHELL HZ GROUNDBIRCH C07-28-079-20
Location: DLS: C07-28-079-20

Permit: 100076681
Well ID: 28611
Well Name: SHELL ET AL HZ GROUNDBIRCH D07-28-079-20
Location: DLS: D07-28-079-20

Permit: 100103954
Well ID: 35109
Well Name: SHELL HZ GROUNDBIRCH E07-28-079-20
Location: DLS: E07-28-079-20

Permit: 100103954
Well ID: 35110
Well Name: SHELL HZ GROUNDBIRCH F07-28-079-20
Location: DLS: F07-28-079-20

Permit: 100114996
Well ID: 43633
Well Name: SHELL HZ GROUNDBIRCH G07-28-079-20
Location: DLS: G07-28-079-20

Authorized by BCER