

## Inspection Report

Permit Holder: Shell Canada Limited  
Inspection: 2026-1604  
Inspection Date: 2026-05-14  
Inspection Outcome: Non-Compliance(s) Found

### Inspection Comment:

5-5-80-21

Signage no concerns.

SCV no venting observed.

Wellhead isolated, chained and locked.

Wellhead is missing a plug on lower valve assembly (see noncompliance).

Pigging area no concerns.

Metering cabinet no concerns.

2 propane tanks with secondary containment no concerns.

Chemical injection system no concerns.

Separator building no concerns.

RTU building no concerns.

An Inspection was conducted and as a result Non-Compliance(s) were found and must be corrected. For specifics on the Non-Compliances, refer to the **Non-Compliance Notice**.

To respond to these Non-Compliances, access the CM-IS Permit Holder Application.

Consideration should be given to checking your other locations for similar Non-Compliances.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100074172  
Well ID: 27455  
Well Name: SHELL HZ GROUND BIRCH 05-05-080-21  
Location: DLS: 05-05-080-21

Permit: 100074172  
Facility ID: 00025208  
Facility Name: SHELL HERITAGE 05-05-080-21 001  
Facility Type: Well Facility  
Location: DLS: 05-05-080-21

---

Authorized by BCER