

Inspection Report

Permit Holder: Shell Canada Limited
Inspection: 2026-1605
Inspection Date: 2026-05-14
Inspection Outcome: Inspected

Inspection Comment:

3-21-80-19

Signage no concerns.

SCV no venting observed.

Metering cabinet no concerns.

Shutdown isolation valve car sealed open.

Actuator no concerns.

Desander no concerns.

All plugs and caps in place.

No concerns identified at time of inspection.

A3-21-80-19

Signage no concerns.

SCV no venting observed.

Metering cabinet no concerns.

Shutdown isolation valve car sealed open.

Actuator no concerns.

Desander no concerns.

All plugs and caps in place.

No concerns identified at time of inspection.

B3-21-80-19

Signage no concerns.

SCV no venting observed.

Metering cabinet no concerns.

Shutdown isolation valve car sealed open.

Actuator no concerns.

Desander no concerns.

All plugs and caps in place.

No concerns identified at time of inspection.

C3-21-80-19

Signage no concerns.

SCV no venting observed.

Metering cabinet no concerns.

Shutdown isolation valve car sealed open.

Actuator no concerns.

Desander no concerns.

All plugs and caps in place.

No concerns identified at time of inspection.

D3-21-80-19

Signage no concerns.

SCV no venting observed.

Metering cabinet no concerns.

Shutdown isolation valve car sealed open.

Actuator no concerns.

Desander no concerns.

All plugs and caps in place.

No concerns identified at time of inspection.

E3-21-80-19

Signage no concerns.

SCV no venting observed.

Metering cabinet no concerns.

Shutdown isolation valve car sealed open.

Actuator no concerns.

Desander no concerns.

All plugs and caps in place.

No concerns identified at time of inspection.

F3-21-80-19

Signage no concerns.

SCV no venting observed.

Metering cabinet no concerns.

Shutdown isolation valve car sealed open.

Actuator no concerns.

Desander no concerns.

All plugs and caps in place.

No concerns identified at time of inspection.

G3-21-80-19

Signage no concerns.

SCV no venting observed.

Metering cabinet no concerns.

Shutdown isolation valve car sealed open.

Actuator no concerns.

Desander no concerns.

All plugs and caps in place.

No concerns identified at time of inspection.

H3-21-80-21

Signage no concerns.

SCV no venting observed.

Metering cabinet no concerns.

Shutdown isolation valve car sealed open.

Actuator no concerns.

Desander no concerns.

All plugs and caps in place.

No concerns identified at time of inspection.

I3-21-80-19

Signage no concerns.

SCV no venting observed.

Metering cabinet no concerns.

Shutdown isolation valve car sealed open.

Actuator no concerns.

Desander no concerns.

All plugs and caps in place.

No concerns identified at time of inspection.

J3-21-80-19

Signage no concerns.

SCV no venting observed.

Metering cabinet no concerns.

Shutdown isolation valve car sealed open.

Actuator no concerns.

Desander no concerns.

All plugs and caps in place.

No concerns identified at time of inspection.

K3-21-80-19

Signage no concerns.

SCV no venting observed.

Metering cabinet no concerns.

Shutdown isolation valve car sealed open.

Actuator no concerns.

Desander no concerns.

All plugs and caps in place.

No concerns identified at time of inspection.

L3-21-80-19

Signage no concerns.

SCV no venting observed.

Metering cabinet no concerns.

Shutdown isolation valve car sealed open.

Actuator no concerns.

Desander no concerns.

All plugs and caps in place.

No concerns identified at time of inspection.

Chemical injection tank with secondary containment no concerns.

Chemical injection system no concerns.

RTU building no concerns.

2 Separator skids no concerns.

Sirius chemical injection system no concerns.

Pigging area no concerns.

All plugs and caps in place.

No concerns identified at time of inspection.

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100100691
Well ID: 32677
Well Name: SHELL HZ GROUNDBIRCH 03-21-080-19
Location: DLS: 03-21-080-19

Permit: 100100691
Well ID: 32678
Well Name: SHELL HZ GROUNDBIRCH A03-21-080-19
Location: DLS: A03-21-080-19

Permit: 100100691
Well ID: 32679
Well Name: SHELL HZ GROUNDBIRCH B03-21-080-19
Location: DLS: B03-21-080-19

Permit: 100100691
Well ID: 32680
Well Name: SHELL HZ GROUNDBIRCH C03-21-080-19
Location: DLS: C03-21-080-19

Permit: 100100691
Well ID: 32681
Well Name: SHELL HZ GROUNDBIRCH D03-21-080-19
Location: DLS: D03-21-080-19

Permit: 100100691
Well ID: 32682
Well Name: SHELL HZ GROUNDBIRCH E03-21-080-19
Location: DLS: E03-21-080-19

Permit: 100100691
Well ID: 32683
Well Name: SHELL HZ GROUNDBIRCH F03-21-080-19
Location: DLS: F03-21-080-19

Permit: 100100691
Well ID: 32684
Well Name: SHELL HZ GROUNDBIRCH G03-21-080-19
Location: DLS: G03-21-080-19

Permit: 100100691
Well ID: 32685
Well Name: SHELL HZ GROUNDBIRCH H03-21-080-19
Location: DLS: H03-21-080-19

Permit: 100100691
Well ID: 32686
Well Name: SHELL HZ GROUNDBIRCH I03-21-080-19
Location: DLS: I03-21-080-19

Permit: 100100691
Well ID: 32687
Well Name: SHELL HZ GROUNDBIRCH J03-21-080-19
Location: DLS: J03-21-080-19

Permit: 100100691
Well ID: 32688
Well Name: SHELL HZ GROUNDBIRCH K03-21-080-19
Location: DLS: K03-21-080-19

Permit: 100100691
Well ID: 32689
Well Name: SHELL HZ GROUNDBIRCH L03-21-080-19
Location: DLS: L03-21-080-19

Permit: 100104449
Facility ID: 00026610
Facility Name: SHELL GROUNDBIRCH 03-21-080-19 001
Facility Type: Well Facility
Location: DLS: 03-21-080-19

Authorized by BCER