

## Inspection Report

Permit Holder: Pacific Canbriam Energy Limited  
Inspection: 2026-1611  
Inspection Date: 2026-05-13  
Inspection Outcome: Inspected

### Inspection Comment:

This inspection is for the stream crossing, classified as an S3, on pipeline project 000025869. The stream bed and banks have been armoured with various sizes of round cobbles and looks good. No concerns were noted at the time of inspection. This pipeline inspection limited in scope to the stream crossing.

The permit condition for line of sight mitigation of every 200m has already been identified and communicated to Pacific Canbriam in last years inspection and will be worked on this summer.

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100114094  
Pipeline Project ID: 000025869  
Segment IDs (Location): 1 (From DLS: 16-32-084-25 To DLS: 08-06-085-25), 2 (From DLS: 16-32-084-25 To DLS: 08-06-085-25), 3 (From DLS: 08-06-085-25 To DLS: 16-32-084-25)

Permit: 100114094  
Permit Condition:  
The Permit Holder must implement line of site mitigations on the pipeline right of way at least every two hundred (200) metres.

---

Authorized by BCER