

## Inspection Report

Permit Holder: Canadian Natural Resources Limited  
Inspection: 2026-1612  
Inspection Date: 2026-05-19  
Inspection Outcome: Inspected

### Inspection Comment:

Site 03-14-081-15 was inspected at or about 1235 hours, it was 10 & cloudy. The following was included in the inspection:

Access and signage: culvert on access road in is exposed, no other concerns

Site: clean and dry

Wellheads: Bull plugs, SCV, locks, leaks, -no concerns - chained, locked all handles, blind flange isolation after the separator building, cement barricades around wellhead

Meter/separator buildings: locks, leaks, caps, vents, - no concerns - out of service

Chemical tanks: leaks, grounds, caps, - no concerns - 2nd containment 1/4 full

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100024576  
Well ID: 12148  
Well Name: CNRL ET AL DOE 03-14-081-15  
Location: DLS: 03-14-081-15

Permit Holder: Canadian Natural Resources Limited

---

Authorized by BCER