

## Inspection Report

Permit Holder: Canadian Natural Resources Limited  
Inspection: 2026-1614  
Inspection Date: 2026-05-19  
Inspection Outcome: Inspected

### Inspection Comment:

Site 10-11-081-15 was inspected at or about 1250 hours, it was 14 & cloudy.  
The following was included in the inspection:  
Access and signage: rutted  
Site: clean and dry  
Wellheads: Bull plugs, SCV, locks, leaks, -SCV gurgling, odorous, failed glove test, bubble test performed - SCV Flow submitted 2025-11-12 reporting 22.70 m3/day  
Meter/separator buildings: locks, leaks, caps, vents, - no concerns - not in service  
Chemical tanks: leaks, grounds, caps, - no concerns

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100010030  
Well ID: 06758  
Well Name: CNRL ET AL DOE 10-11-081-15  
Location: DLS: 10-11-081-15

Permit Holder: Canadian Natural Resources Limited

---

Authorized by BCER