

## Inspection Report

Permit Holder: PETRONAS Energy Canada Ltd.  
Inspection: 2026-1616  
Inspection Date: 2026-05-14  
Inspection Outcome: Non-Compliance(s) Found

### Inspection Comment:

This is a single well pad. The well head is properly suspended with all valves chained and locked and flow line disconnected. The well facility has been disconnected and the pipeline deactivated and documented as such in KERMIT.  
This is a clean site except for some yellow jacket and carbon pipe that has been hidden by grass for a long time and that has been written as a deficiency.

An Inspection was conducted and as a result Non-Compliance(s) were found and must be corrected. For specifics on the Non-Compliances, refer to the **Non-Compliance Notice**.

To respond to these Non-Compliances, access the CM-IS Permit Holder Application.

Consideration should be given to checking your other locations for similar Non-Compliances.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100051956  
Well ID: 20707  
Well Name: PETRONAS ALTARES C- 020-H/094-B-08  
Location: NTS: C- 020-H/094-B-08

Permit: 100051956  
Facility ID: 00021880  
Facility Name: PETRONAS ALTARES C-020-H/094-B-08 001  
Facility Type: Well Facility  
Location: NTS: C- 020-H/094-B-08

---

Authorized by BCER