

Inspection Report

Permit Holder: PETRONAS Energy Canada Ltd.
Inspection: 2026-1619
Inspection Date: 2026-05-14
Inspection Outcome: Inspected

Inspection Comment:

This is a single well pad with a properly suspended well with valves chained and locked and flowline disconnected. The simple well facility has been suspended properly. The chemical tanks appear to have been emptied and with the valves closed. The pipelines have been deactivated properly and signed as such.

This well pad was tear dropped many years ago. There is great conifer and some deciduous tree recruitment on the original wider clearing.

The pipeline sign has fallen over on the edge of the tear drop and it has previously been hidden by grass but is visible now and should be reinstalled.

No concerns noted at the time of inspection.

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100048869
Well ID: 19641
Well Name: PETRONAS ALTARES C- 030-H/094-B-08
Location: NTS: C- 030-H/094-B-08

Permit: 100048869
Facility ID: 00021295
Facility Name: PETRONAS ALTARES C-030-H/094-B-08 001
Facility Type: Well Facility
Location: NTS: C- 030-H/094-B-08

Authorized by BCER