

Inspection Report

Permit Holder: Ovintiv Canada ULC
Inspection: 2026-1624
Inspection Date: 2026-05-14
Inspection Outcome: Inspected

Inspection Comment:

Access inspected. Access signage detached. Notified operator who corrected same day. See pictures.

Pad clean.

Inspect wells. Barricaded. No SCV flow observed. Meters inspected. Signage clear and legible. 0 well has burst plate installed on SCV.

Pig barrel inspected.

Associated pipeline well vegetated.

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100055866
Well ID: 21644
Well Name: OVV ECOG ET AL HZ SUNDOWN B- 063-I/093-P-07
Location: NTS: B- 063-I/093-P-07

Permit: 100055867
Well ID: 21645
Well Name: OVV ECOG ET AL HZ SUNDOWN B-A063-I/093-P-07
Location: NTS: B-A063-I/093-P-07

Permit: 100055866
Facility ID: 00022322
Facility Name: OVV SWAN B-063-I/093-P-07 001
Facility Type: Well Facility
Location: NTS: B- 063-I/093-P-07



Inspection Number: 2026-1624
Inspection Date: 2026-05-14

Letter ID: L2602314
Letter Date: 2026-05-21

Authorized by BCER