

## Inspection Report

Permit Holder: Shell Canada Limited  
Inspection: 2026-1645  
Inspection Date: 2026-05-20  
Inspection Outcome: Inspected

### Inspection Comment:

A9-4-80-19

Signage no concerns.

SCV no venting observed.

Wellhead isolated, chained and locked.

Metering cabinet no concerns.

Chemical tank with secondary containment no concerns.

Chemical injection system no concerns.

All plugs and caps in place.

No concerns identified at time of inspection.

B9-4-80-19

Signage no concerns.

SCV no venting observed.

Wellhead isolated, chained and locked.

Metering cabinet no concerns.

Chemical tank with secondary containment no concerns.

Chemical injection system no concerns.

Propane tank bonded to ground.

All plugs and caps in place.

No concerns identified at time of inspection.

16-4-80-19

Signage no concerns.

SCV no venting observed.

Wellhead isolated, chained and locked.

Metering cabinet no concerns.

Chemical tank with secondary containment no concerns.

Chemical injection system no concerns.

Propane tank bonded to ground.

All plugs and caps in place.

No concerns identified at time of inspection.

A16-4-80-19

Signage no concerns.

SCV no venting observed.

Metering cabinet no concerns.

Shutdown isolation valve car-sealed.

Actuator no concerns.

All plugs and caps in place.

No concerns identified at time of inspection.

B16-4-80-19

Signage no concerns.

SCV no venting observed.

Metering cabinet no concerns.

Shutdown isolation valve car-sealed.

Actuator no concerns.

All plugs and caps in place.

No concerns identified at time of inspection.

C16-4-80-19

Signage no concerns.

SCV no venting observed.

Metering cabinet no concerns.

Shutdown isolation valve car-sealed.

Actuator no concerns.

All plugs and caps in place.

No concerns identified at time of inspection.

D16-4-80-19

Signage no concerns.

SCV no venting observed.

Metering cabinet no concerns.

Shutdown isolation valve car-sealed.

Actuator no concerns.

All plugs and caps in place.

No concerns identified at time of inspection.

E16-4-80-19

Signage no concerns.

SCV no venting observed.

Wellhead chained and locked.

Metering cabinet no concerns.

Shutdown isolation valve car-sealed.

Actuator no concerns.

All plugs and caps in place.

No concerns identified at time of inspection.

F16-4-80-19

Signage no concerns.

SCV no venting observed.

Wellhead isolated, chained and locked.

All caps and plugs in place.

No concerns identified at time of inspection.

G16-4-80-19

Signage no concerns.

SCV no venting observed.

Metering cabinet no concerns.

Shutdown isolation valve car-sealed.

Actuator no concerns.

All plugs and caps in place.

No concerns identified at time of inspection.

Facility

Desander no concerns.

Chemical tank with secondary containment no concerns.

Chemical injection system no concerns.

Sirius chemical injection system and tank with secondary containment no concerns.

RTU no concerns.

Test separator no concerns.

Group separator no concerns.

Pigging area no concerns.

All plugs and caps in place.

No concerns identified at time of inspection.

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100063177  
Well ID: 23753  
Well Name: SHELL HZ SATURN A09-04-080-19  
Location: DLS: A09-04-080-19

Permit: 100064047  
Well ID: 24001  
Well Name: SHELL HZ SATURN B09-04-080-19  
Location: DLS: B09-04-080-19

Permit: 100068177  
Well ID: 25297  
Well Name: SHELL HZ SATURN 16-04-080-19  
Location: DLS: 16-04-080-19

Permit: 100100833  
Well ID: 32496  
Well Name: SHELL HZ SATURN A16-04-080-19  
Location: DLS: A16-04-080-19

Permit: 100100833  
Well ID: 32497  
Well Name: SHELL HZ SATURN B16-04-080-19  
Location: DLS: B16-04-080-19

Permit: 100100833  
Well ID: 32498  
Well Name: SHELL HZ SATURN C16-04-080-19  
Location: DLS: C16-04-080-19

Permit: 100100833  
Well ID: 32499  
Well Name: SHELL HZ SATURN D16-04-080-19  
Location: DLS: D16-04-080-19

Permit: 100100833  
Well ID: 32500  
Well Name: SHELL HZ SATURN E16-04-080-19  
Location: DLS: E16-04-080-19

Permit: 100100833  
Well ID: 32501  
Well Name: SHELL HZ SATURN F16-04-080-19  
Location: DLS: F16-04-080-19

Permit: 100100833  
Well ID: 32502  
Well Name: SHELL HZ SATURN G16-04-080-19  
Location: DLS: G16-04-080-19

Permit: 100063177  
Facility ID: 00023299  
Facility Name: SHELL HERITAGE 09-04-080-19 001  
Facility Type: Well Facility  
Location: DLS: 09-04-080-19

Permit: 100064047  
Facility ID: 00023435  
Facility Name: SHELL HERITAGE 09-04-080-19 002  
Facility Type: Well Facility  
Location: DLS: 09-04-080-19

Permit: 100068177  
Facility ID: 00024086  
Facility Name: SHELL HERITAGE 16-04-080-19 001  
Facility Type: Well Facility  
Location: DLS: 16-04-080-19

Permit: 100115516  
Facility ID: 00027569  
Facility Name: SHELL GROUNDBIRCH 16-04-080-19 002  
Facility Type: Well Facility  
Location: DLS: 16-04-080-19

---

Authorized by BCER