

Inspection Report

Permit Holder: Shell Canada Limited
Inspection: 2026-1646
Inspection Date: 2026-05-20
Inspection Outcome: Inspected

Inspection Comment:

Site fully gravelled with header area in place, has 6 new wells drilled ready for christmas trees and are fenced off.

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100112738
Well ID: 41703
Well Name: SHELL HZ GROUNDBIRCH A11-04-080-19
Location: DLS: A11-04-080-19

Permit: 100112738
Well ID: 41704
Well Name: SHELL HZ GROUNDBIRCH B11-04-080-19
Location: DLS: B11-04-080-19

Permit: 100112738
Well ID: 41705
Well Name: SHELL HZ GROUNDBIRCH C11-04-080-19
Location: DLS: C11-04-080-19

Permit: 100112738
Well ID: 41706
Well Name: SHELL HZ GROUNDBIRCH D11-04-080-19
Location: DLS: D11-04-080-19

Permit: 100112738
Well ID: 41707
Well Name: SHELL HZ GROUNDBIRCH 06-04-080-19
Location: DLS: 06-04-080-19

Permit: 100112738
Well ID: 41708
Well Name: SHELL HZ GROUNDBIRCH A06-04-080-19
Location: DLS: A06-04-080-19



Inspection Number: 2026-1646
Inspection Date: 2026-05-20

Letter ID: L2602339
Letter Date: 2026-05-22

Authorized by BCER