

## Inspection Report

Permit Holder: Canlin Energy Corporation  
Inspection: 2026-1651  
Inspection Date: 2026-05-21  
Inspection Outcome: Inspected

### Inspection Comment:

Site 06-33-081-15 was inspected at or about hours, it was 10 & sunny. The following was included in the inspection:

Access and signage: no concerns

Site: some ruts, clean, dry

Wellheads: Bull plugs, SCV, locks, leaks, -no concerns

Meter/separator buildings: locks, leaks, caps, vents, - no concerns

Chemical tanks: leaks, grounds, caps, - no concerns

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100033516  
Well ID: 14998  
Well Name: CANLIN ET AL PARKLAND 06-33-081-15  
Location: DLS: 06-33-081-15

Permit: 100036523  
Well ID: 16057  
Well Name: CANLIN ET AL PARKLAND A06-33-081-15  
Location: DLS: A06-33-081-15

Permit: 100036523  
Facility ID: 00020155  
Facility Name: CANLIN PARKLAND 06-33-081-15 002  
Facility Type: Well Facility  
Location: DLS: 06-33-081-15

Permit Holder: Canlin Energy Corporation

---

Authorized by BCER