

## Inspection Report

Permit Holder: Shell Canada Limited  
Inspection: 2026-1652  
Inspection Date: 2026-05-20  
Inspection Outcome: Inspected

### Inspection Comment:

1-23-80-19

Signage no concerns.

SCV no venting observed.

Metering cabinet no concerns.

Shutdown isolation valve car-sealed.

Actuator no concerns.

Desander no concerns.

All plugs and caps in place.

No concerns identified at time of inspection.

A1-23-80-19

Signage no concerns.

SCV no venting observed.

Metering cabinet no concerns.

Shutdown isolation valve car-sealed.

Actuator no concerns.

Desander no concerns.

All plugs and caps in place.

No concerns identified at time of inspection.

B1-23-80-19

Signage no concerns.

SCV no venting observed.

Metering cabinet no concerns.

Shutdown isolation valve car-sealed.

Actuator no concerns.

Desander no concerns.

All plugs and caps in place.

No concerns identified at time of inspection.

C1-23-80-19

Signage no concerns.

SCV no venting observed.

Metering cabinet no concerns.

Shutdown isolation valve car-sealed.

Actuator no concerns.

Desander no concerns.

All plugs and caps in place.

No concerns identified at time of inspection.

D1-23-80-19

Signage no concerns.

SCV no venting observed.

Metering cabinet no concerns.

Shutdown isolation valve car-sealed.

Actuator no concerns.

Desander no concerns.

All plugs and caps in place.

No concerns identified at time of inspection.

E1-23-80-19

Signage no concerns.

SCV no venting observed.

Metering cabinet no concerns.

Shutdown isolation valve car-sealed.

Actuator no concerns.

Desander no concerns.

All plugs and caps in place.

No concerns identified at time of inspection.

F1-23-80-19

Signage no concerns.

SCV no venting observed.

Metering cabinet no concerns.

Shutdown isolation valve car-sealed.

Actuator no concerns.

Desander no concerns.

All plugs and caps in place.

No concerns identified at time of inspection.

Facility

Chemical tank with secondary containment no concerns.

Chemical injection system no concerns.

RTU building no concerns.

Test separator no concerns.

Group separator no concerns.

Sirius chemical injection system no concerns.

Header/pigging area no concerns.

All plugs and caps in place.

No concerns identified at time of site inspection.

A satisfactory inspection was conducted.

The following were the only items that were inspected during this inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this inspection.

Permit: 100113167  
Well ID: 41987  
Well Name: SHELL HZ GROUNDBIRCH 01-23-080-19  
Location: DLS: 01-23-080-19

Permit: 100113167  
Well ID: 41988  
Well Name: SHELL HZ GROUNDBIRCH A01-23-080-19  
Location: DLS: A01-23-080-19

Permit: 100113167  
Well ID: 41989  
Well Name: SHELL HZ GROUNDBIRCH B01-23-080-19  
Location: DLS: B01-23-080-19

Permit: 100113167  
Well ID: 41990  
Well Name: SHELL HZ GROUNDBIRCH C01-23-080-19  
Location: DLS: C01-23-080-19

Permit: 100113167  
Well ID: 41991  
Well Name: SHELL HZ GROUNDBIRCH D01-23-080-19  
Location: DLS: D01-23-080-19

Permit: 100113167  
Well ID: 41992  
Well Name: SHELL HZ GROUNDBIRCH E01-23-080-19  
Location: DLS: E01-23-080-19

Permit: 100113167  
Well ID: 41993  
Well Name: SHELL HZ GROUNDBIRCH F01-23-080-19  
Location: DLS: F01-23-080-19

Permit: 100119486  
Facility ID: 00028178  
Facility Name: SHELL GROUNDBIRCH 01-23-080-19 001  
Facility Type: Well Facility  
Location: DLS: 01-23-080-19

---

Authorized by BCER