

Inspection Report

Permit Holder: Canadian Natural Resources Limited
Inspection: 2026-1654
Inspection Date: 2026-05-21
Inspection Outcome: Inspected

Inspection Comment:

9-21-81-19

Signage no concerns.

SCV no venting observed.

Shutdown isolation valve locked.

Actuator no concerns.

All plugs and caps in place.

No concerns identified at time of inspection.

A9-21-81-19

Signage no concerns.

SCV no venting observed.

Shutdown isolation valve locked.

Actuator no concerns.

All plugs and caps in place.

No concerns identified at time of inspection.

B9-21-81-19

Signage no concerns.

SCV no venting observed.

Wellhead isolated, chained and locked.

All plugs and caps in place.

No concerns identified at time of inspection.

C9-21-81-19

Signage no concerns.

SCV no venting observed.

Shutdown isolation valve locked.

Actuator no concerns.

All plugs and caps in place.

No concerns identified at time of inspection.

D9-21-81-19

Signage no concerns.

SCV no venting observed.

Shutdown isolation valve locked.

Actuator no concerns.

All plugs and caps in place.

No concerns identified at time of inspection.

E9-21-81-19

Signage no concerns.

SCV no venting observed.

Shutdown isolation valve locked.

Actuator no concerns.

All plugs and caps in place.

No concerns identified at time of inspection.

Facility

Metering/test separator building no concerns.

Chemical injection system no concerns.

Large methanol tank with secondary containment no concerns.

All plugs and caps in place.

No concerns identified at time of inspection.

F9-21-81-19

Signage no concerns.

SCV no venting observed.

Shutdown isolation valve locked.

Actuator no concerns.

All plugs and caps in place.

No concerns identified at time of inspection.

G9-21-81-19

Signage no concerns.

SCV no venting observed.

Shutdown isolation valve locked.

Actuator no concerns.

All plugs and caps in place.

No concerns identified at time of inspection.

H9-21-81-19

Signage no concerns.

SCV no venting observed.

Shutdown isolation valve locked.

Actuator no concerns.

All plugs and caps in place.

No concerns identified at time of inspection.

I9-21-81-19

Signage no concerns.

SCV no venting observed.

Shutdown isolation valve locked.

Actuator no concerns.

All plugs and caps in place.

No concerns identified at time of inspection.

J9-21-81-19

Signage no concerns.

SCV no venting observed.

Shutdown isolation valve locked.

Actuator no concerns.

All plugs and caps in place.

No concerns identified at time of inspection.

Facility

Metering/test separator building no concerns.

Chemical injection systems no concerns.

Chemical tank with secondary containment, chemical injection system no concerns.

Flare knock-out building no concerns.

Flare stack no concerns.

All plugs and caps in place.

No concerns identified at time of inspection.

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100073195
Well ID: 27014
Well Name: CNRL HZ SEPTIMUS 09-21-081-19
Location: DLS: 09-21-081-19

Permit: 100073494
Well ID: 27245
Well Name: CNRL HZ SEPTIMUS B09-21-081-19
Location: DLS: B09-21-081-19

Permit: 100073503
Well ID: 27244
Well Name: CNRL HZ SEPTIMUS A09-21-081-19
Location: DLS: A09-21-081-19

Permit: 100074607
Well ID: 27797
Well Name: CNRL HZ SEPTIMUS C09-21-081-19
Location: DLS: C09-21-081-19

Permit: 100074608
Well ID: 27798
Well Name: CNRL HZ SEPTIMUS D09-21-081-19
Location: DLS: D09-21-081-19

Permit: 100074609
Well ID: 27800
Well Name: CNRL HZ SEPTIMUS E09-21-081-19
Location: DLS: E09-21-081-19

Permit: 100078454
Well ID: 29458
Well Name: CNRL HZ SEPTIMUS F09-21-081-19
Location: DLS: F09-21-081-19

Permit: 100078455
Well ID: 29465
Well Name: CNRL HZ SEPTIMUS G09-21-081-19
Location: DLS: G09-21-081-19

Permit: 100078456
Well ID: 29466
Well Name: CNRL HZ SEPTIMUS H09-21-081-19
Location: DLS: H09-21-081-19

Permit: 100078457
Well ID: 29471
Well Name: CNRL HZ SEPTIMUS I09-21-081-19
Location: DLS: I09-21-081-19

Permit: 100078458
Well ID: 29472
Well Name: CNRL HZ SEPTIMUS J09-21-081-19
Location: DLS: J09-21-081-19

Permit: 100073195
Facility ID: 00017919
Facility Name: CNRL SEPTIMUS 09-21-081-19 001
Facility Type: Well Facility
Location: DLS: 09-21-081-19

Authorized by BCER