

Inspection Report

Permit Holder: Canadian Natural Resources Limited
Inspection: 2026-1655
Inspection Date: 2026-05-21
Inspection Outcome: Inspected

Inspection Comment:

3-32-81-19

Signage no concerns.

SCV no venting observed.

Wellhead isolated, chained and locked.

All plugs and caps in place.

No concerns identified at time of inspection.

A3-32-81-19

Signage no concerns.

SCV no venting observed.

Shutdown isolation valve locked.

Actuator no concerns.

All plugs and caps in place.

No concerns identified at time of inspection.

B3-32-81-19

Signage no concerns.

SCV no venting observed.

Shutdown isolation valve locked.

Actuator no concerns.

All plugs and caps in place.

No concerns identified at time of inspection.

C3-32-81-19

Signage no concerns.

SCV no venting observed.

Shutdown isolation valve locked.

Actuator no concerns.

All plugs and caps in place.

No concerns identified at time of inspection.

D3-32-81-19

Signage no concerns.

SCV no venting observed.

Shutdown isolation valve locked.

Actuator no concerns.

All plugs and caps in place.

No concerns identified at time of inspection.

E3-32-81-19

Signage no concerns.

SCV no venting observed.

Shutdown isolation valve locked.

Actuator no concerns.

All plugs and caps in place.

No concerns identified at time of inspection.

F3-32-81-19

Signage no concerns.

SCV no venting observed.

Shutdown isolation valve locked.

Actuator no concerns.

All plugs and caps in place.

No concerns identified at time of inspection.

Facility

Metering/test separator building no concerns.

Flare knock-out building no concerns.

Flare stack no concerns.

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100065392

Well ID: 24221

Well Name: CNRL SEPTIMUS 03-32-081-19

Location: DLS: 03-32-081-19

Permit: 100065686

Well ID: 24507

Well Name: CNRL HZ SEPTIMUS A03-32-081-19

Location: DLS: A03-32-081-19

Permit: 100069957

Well ID: 25935

Well Name: CNRL HZ SEPTIMUS B03-32-081-19

Location: DLS: B03-32-081-19

Permit: 100070724

Well ID: 26153

Well Name: CNRL HZ SEPTIMUS C03-32-081-19

Location: DLS: C03-32-081-19

Permit: 100070737
Well ID: 26154
Well Name: CNRL HZ SEPTIMUS D03-32-081-19
Location: DLS: D03-32-081-19

Permit: 100070749
Well ID: 26161
Well Name: CNRL HZ SEPTIMUS E03-32-081-19
Location: DLS: E03-32-081-19

Permit: 100070750
Well ID: 26162
Well Name: CNRL HZ SEPTIMUS F03-32-081-19
Location: DLS: F03-32-081-19

Permit: 100065686
Facility ID: 00023719
Facility Name: CNRL HERITAGE 03-32-081-19 002
Facility Type: Well Facility
Location: DLS: 03-32-081-19

Permit: 100069957
Facility ID: 00024413
Facility Name: CNRL HERITAGE 03-32-081-19 005
Facility Type: Well Facility
Location: DLS: 03-32-081-19

Permit: 100070724
Facility ID: 00024538
Facility Name: CNRL HERITAGE 03-32-081-19 006
Facility Type: Well Facility
Location: DLS: 03-32-081-19

Permit: 100070737
Facility ID: 00024539
Facility Name: CNRL HERITAGE 03-32-081-19 007
Facility Type: Well Facility
Location: DLS: 03-32-081-19

Permit: 100070749
Facility ID: 00024546
Facility Name: CNRL HERITAGE 03-32-081-19 008
Facility Type: Well Facility
Location: DLS: 03-32-081-19

Permit: 100070750
Facility ID: 00024547
Facility Name: CNRL HERITAGE 03-32-081-19 009
Facility Type: Well Facility
Location: DLS: 03-32-081-19

Authorized by BCER