

Inspection Report

Permit Holder: Tourmaline Oil Corp.
Inspection: 2026-1656
Inspection Date: 2026-05-21
Inspection Outcome: Inspected

Inspection Comment:

A4-34-81-19

Signage no concerns.

SCV no venting observed.

Shutdown isolation valve locked.

Actuator no concerns.

Chemical tank with secondary containment and chemical injections system no concerns.

All plugs and caps in place.

No concerns identified at time of inspection.

B4-34-81-19

Signage no concerns.

SCV no venting observed.

Shutdown isolation valve locked.

Actuator no concerns.

All plugs and caps in place.

No concerns identified at time of inspection.

C4-34-81-19

Signage no concerns.

SCV no venting observed.

Shutdown isolation valve locked.

Actuator no concerns.

All plugs and caps in place.

No concerns identified at time of inspection.

D4-34-81-19

Signage no concerns.

SCV no venting observed.

Shutdown isolation valve locked.

Actuator no concerns.

Chemical tank with secondary containment and chemical injection system no concerns.

All plugs and caps in place.

No concerns identified at time of inspection.

E4-34-81-19

Signage no concerns.

SCV no venting observed.

Shutdown isolation valve locked.

Actuator no concerns.

Chemical tank with secondary containment and chemical injection system no concerns.

All plugs and caps in place.

No concerns identified at time of inspection.

Pigging area no concerns.

3 propane tanks bonded to ground.

Chemical tank with secondary containment and chemical injection system no concerns.

All plugs and caps in place.

No concerns identified at time of site inspection.

A satisfactory inspection was conducted.

The following were the only items that were inspected during this inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this inspection.

Permit: 100071513
Well ID: 26417
Well Name: TOURMALINE HZ SEPTIMUS A04-34-081-19
Location: DLS: A04-34-081-19

Permit: 100071514
Well ID: 26418
Well Name: TOURMALINE HZ SEPTIMUS B04-34-081-19
Location: DLS: B04-34-081-19

Permit: 100071515
Well ID: 26419
Well Name: TOURMALINE HZ SEPTIMUS C04-34-081-19
Location: DLS: C04-34-081-19

Permit: 100077586
Well ID: 29038
Well Name: TOURMALINE HZ SEPTIMUS D04-34-081-19
Location: DLS: D04-34-081-19

Permit: 100077587
Well ID: 29039
Well Name: TOURMALINE HZ SEPTIMUS E04-34-081-19
Location: DLS: E04-34-081-19

Permit: 100071513
Facility ID: 00024675
Facility Name: TOURMALINE HERITAGE 04-34-081-19 001
Facility Type: Well Facility
Location: DLS: 04-34-081-19

Permit: 100071514
Facility ID: 00024676
Facility Name: TOURMALINE HERITAGE 04-34-081-19 002
Facility Type: Well Facility
Location: DLS: 04-34-081-19

Permit: 100071515
Facility ID: 00024677
Facility Name: TOURMALINE HERITAGE 04-34-081-19 003
Facility Type: Well Facility
Location: DLS: 04-34-081-19

Permit: 100077586
Facility ID: 00025876
Facility Name: TOURMALINE HERITAGE 04-34-081-19 004
Facility Type: Well Facility
Location: DLS: 04-34-081-19

Permit: 100077587
Facility ID: 00025877
Facility Name: TOURMALINE HERITAGE 04-34-081-19 005
Facility Type: Well Facility
Location: DLS: 04-34-081-19

Authorized by BCER