

Inspection Report

Permit Holder: Canadian Natural Resources Limited
Inspection: 2026-1657
Inspection Date: 2026-05-21
Inspection Outcome: Inspected

Inspection Comment:

10-27-81-19

Signage no concerns.

SCV no venting observed.

Shutdown isolation valve locked.

Actuator no concerns.

All plugs and caps in place.

No concerns identified at time of inspection.

A10-27-81-19

Signage no concerns.

SCV no venting observed.

Shutdown isolation valve locked.

Actuator no concerns.

All plugs and caps in place.

No concerns identified at time of inspection.

B10-27-81-19

Signage no concerns.

SCV no venting observed.

Shutdown isolation valve locked.

Actuator no concerns.

All plugs and caps in place.

No concerns identified at time of inspection.

7-27-81-19

Signage no concerns.

SCV no venting observed.

Shutdown isolation valve locked.

Actuator no concerns.

All plugs and caps in place.

No concerns identified at time of inspection.

A7-27-81-19

Signage no concerns.

SCV no venting observed.

Shutdown isolation valve locked.

Actuator no concerns.

All plugs and caps in place.

No concerns identified at time of inspection.

B7-27-81-19

Signage no concerns.

SCV no venting observed.

Wellhead chained and locked.

Shutdown isolation valve locked.

Actuator no concerns.

All plugs and caps in place.

No concerns identified at time of inspection.

C7-27-81-19

Signage no concerns.

SCV no venting observed.

Shutdown isolation valve locked.

Actuator no concerns.

All plugs and caps in place.

No concerns identified at time of inspection.

D7-27-81-19

Signage no concerns.

SCV no venting observed.

Shutdown isolation valve locked.

Actuator no concerns.

All plugs and caps in place.

No concerns identified at time of inspection.

Facility

Metering/separator building no concerns.

TEG no concerns.

Flare knock-out building no concerns.

Flare stack no concerns.

Methanol tank with secondary containment no concerns.

Chemical injection system no concerns.

All plugs and caps in place.

No concerns identified at time of site inspection.

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100072646
Well ID: 26685
Well Name: CNRL HZ SEPTIMUS 10-27-081-19
Location: DLS: 10-27-081-19

Permit: 100073341
Well ID: 27208
Well Name: CNRL HZ SEPTIMUS A10-27-081-19
Location: DLS: A10-27-081-19

Permit: 100073342
Well ID: 27209
Well Name: CNRL HZ SEPTIMUS B10-27-081-19
Location: DLS: B10-27-081-19

Permit: 100073367
Well ID: 27210
Well Name: CNRL HZ SEPTIMUS 07-27-081-19
Location: DLS: 07-27-081-19

Permit: 100073368
Well ID: 27211
Well Name: CNRL HZ SEPTIMUS A07-27-081-19
Location: DLS: A07-27-081-19

Permit: 100073369
Well ID: 27212
Well Name: CNRL HZ SEPTIMUS B07-27-081-19
Location: DLS: B07-27-081-19

Permit: 100073370
Well ID: 27213
Well Name: CNRL HZ SEPTIMUS C07-27-081-19
Location: DLS: C07-27-081-19

Permit: 100073443
Well ID: 27224
Well Name: CNRL HZ SEPTIMUS D07-27-081-19
Location: DLS: D07-27-081-19

Permit: 100072646
Facility ID: 00024816
Facility Name: CNRL HERITAGE 10-27-081-19 001
Facility Type: Well Facility
Location: DLS: 10-27-081-19

Permit: 100073341
Facility ID: 00025067
Facility Name: CNRL HERITAGE 10-27-081-19 002
Facility Type: Well Facility
Location: DLS: 10-27-081-19

Permit: 100073342
Facility ID: 00025068
Facility Name: CNRL HERITAGE 10-27-081-19 003
Facility Type: Well Facility
Location: DLS: 10-27-081-19

Permit: 100073367
Facility ID: 00025069
Facility Name: CNRL SEPTIMUS 07-27-081-19 001
Facility Type: Well Facility
Location: DLS: 07-27-081-19

Permit: 100073368
Facility ID: 00025070
Facility Name: CNRL HERITAGE 07-27-081-19 002
Facility Type: Well Facility
Location: DLS: 07-27-081-19

Permit: 100073369
Facility ID: 00025071
Facility Name: CNRL HERITAGE 07-27-081-19 003
Facility Type: Well Facility
Location: DLS: 07-27-081-19

Permit: 100073370
Facility ID: 00025072
Facility Name: CNRL HERITAGE 07-27-081-19 004
Facility Type: Well Facility
Location: DLS: 07-27-081-19



Permit: 100073443
Facility ID: 00025080
Facility Name: CNRL HERITAGE 07-27-081-19 005
Facility Type: Well Facility
Location: DLS: 07-27-081-19

Authorized by BCER