

Inspection Report

Permit Holder: ConocoPhillips Canada Resources Corp.
Inspection: 2026-1659
Inspection Date: 2026-05-20
Inspection Outcome: Inspected

Inspection Comment:

- * Travel to COP HZ BLUEBERRY 14-23-088-25, sign in site orientation
- * meet and greet with site supervisors discuss operations and review documents
- * conduct walk around and inspection.
- * discuss inspection with site supervisors.
- * no concerns with this inspection.
- * sign out return to Dawson Creek

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100118245
Well ID: 55942
Well Name: COP HZ BLUEBERRY M14-23-088-25
Location: DLS: M14-23-088-25

Authorized by BCER