

Inspection Report

Permit Holder: Tourmaline Oil Corp.
Inspection: 2026-1665
Inspection Date: 2026-05-21
Inspection Outcome: Inspected

Inspection Comment:

Officer Selected inspection of surface equipment on site.

Performed inspection of location at 1550HRS.

Access road- Vegetation growing on access road. No concerns at the time of inspection.

Lease environment- Vegetation on lease. No erosion sediment or water runoff concerns.

Lease Equipment: Wellhead Abandoned. Surface equipment removed from site.
Signage in place at lease entrance, Company name indicates Bonavista (See attached). No concerns at the time of inspection.

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100003456
Well ID: 02593
Well Name: TOURMALINE ET AL RIGEL 10-35-088-18
Location: DLS: 10-35-088-18

Authorized by BCER