

Inspection Report

Permit Holder: Enercapita Energy Ltd.
Inspection: 2026-1669
Inspection Date: 2026-05-21
Inspection Outcome: Inspected

Inspection Comment:**COMMENTS:**

- active electric pumpjack. No SCVF
- lease, access and signage are compliant.

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100009314
Well ID: 06349
Well Name: ENERCAPITA ET AL BOUNDARY 02-29-085-13
Location: DLS: 02-29-085-13

Authorized by BCER