

Inspection Report

Permit Holder: Whitecap Resources Inc.
Inspection: 2026-1672
Inspection Date: 2026-05-21
Inspection Outcome: Inspected

Inspection Comment:

COMMENTS:

6-29-85-13:

-active electric pumpjack. No SCVF

A6-29-85-13:

-abandoned well with sign. Some ground/contamination monitoring well posts onsite. Also, two holes in middle of lease approximately 3 feet deep and 3 feet in circumference.

*lease does not look to be bermed (oil well) and well sits beside a marsh and pond area. Please assess...

signage and access are compliant.

A satisfactory inspection was conducted.

The following were the only items that were inspected during this inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this inspection.

Permit: 100000746
Well ID: 00591
Well Name: WHITECAP ET AL BOUNDARY 06-29-085-13
Location: DLS: 06-29-085-13

Permit: 100009797
Well ID: 06631
Well Name: WHITECAP ET AL BOUNDARY A06-29-085-13
Location: DLS: A06-29-085-13

Authorized by BCER