

## Inspection Report

Permit Holder: Enercapita Energy Ltd.  
Inspection: 2026-1674  
Inspection Date: 2026-05-21  
Inspection Outcome: Inspected

### Inspection Comment:

#### COMMENTS:

-abandoned well. There is some staining on the ground in the old wellhead area.

-lease and access are compliant.

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100010090  
Well ID: 06801  
Well Name: ENERCAPITA ET AL BOUNDARY 08-29-085-13  
Location: DLS: 08-29-085-13

Permit: 100109253  
Road Number: 05480  
Segment IDs (Location): 002 (From DLS: 07-29-085-13 To DLS: 08-29-085-13)

---

Authorized by BCER