

Inspection Report

Permit Holder: Tourmaline Oil Corp.
Inspection: 2026-1678
Inspection Date: 2026-05-22
Inspection Outcome: Inspected

Inspection Comment:

Access and access signage inspected. Flammable sticker is not legible.

Pad clean. Line heater internal parts stored on site.

Inspect well. Signage clear and legible. Flammable sticker also faded.
Barricades present. No SCV flow observed. ESD closed. Amont is in the override position. Spoke to production compliance operator, who attended site same day to replace stickers and correct Amont. See photos.

Inspect meter building.

Inspect pig barrel.

Associated pipeline well vegetated.

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100066345
Well ID: 24572
Well Name: TOURMALINE SUNDOWN D- 066-A/093-P-10
Location: NTS: D- 066-A/093-P-10

Permit: 100066345
Facility ID: 00023757
Facility Name: TOURMALINE SUNDOWN D-066-A/093-P-10 001
Facility Type: Well Facility
Location: NTS: D- 066-A/093-P-10

Authorized by BCER