

## Inspection Report

Permit Holder: Whitecap Resources Inc.  
Inspection: 2026-1681  
Inspection Date: 2026-05-21  
Inspection Outcome: Inspected

### Inspection Comment:

#### COMMENTS:

3-31-85-13:

-active electric pumpjack. No SCVF

A3-31-85-13:

-as per the location signage, this well is signed as B3-31-85-13 which, as per the IRIS database is incorrect. This well should be signed as A3-31-85-13 (WA#26406).

-I walked into location. Wellhead only, valves chained and locked.

-4 joints of piping/casing lying on lease and an earth berm approximately 50'W x 60'L with the liner remaining in place.

A satisfactory inspection was conducted.

The following were the only items that were inspected during this inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this inspection.

Permit: 100003843  
Well ID: 02886  
Well Name: WHITECAP ET AL BOUNDARY 03-31-085-13  
Location: DLS: 03-31-085-13

Permit: 100072475  
Well ID: 26406  
Well Name: WHITECAP ET AL BOUNDARY A03-31-085-13  
Location: DLS: A03-31-085-13

---

Authorized by BCER