

Inspection Report

Permit Holder: Whitecap Resources Inc.
Inspection: 2026-1685
Inspection Date: 2026-05-21
Inspection Outcome: Inspected

Inspection Comment:

COMMENTS:

-wellhead valves chained and locked. Flowline is disconnected from the wellhead.
Inactive pumpjack remains in place disconnected from well.

-No SCVF

-lease, access and signage are compliant.

A satisfactory inspection was conducted.

The following were the only items that were inspected during this inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this inspection.

Permit: 100003903
Well ID: 02930
Well Name: WHITECAP BOUNDARY 06-32-085-13
Location: DLS: 06-32-085-13

Authorized by BCER