

## Inspection Report

Permit Holder: Ovintiv Canada ULC  
Inspection: 2026-1688  
Inspection Date: 2026-05-22  
Inspection Outcome: Inspected

### Inspection Comment:

Inspect access signage. Clear and legible.

Pad has some garbage and misc. tubing and valves on site (removed for the suspension).

Inspect well. Wellhead suspended, valve handles removed. Barricaded. No signage on wellhead. Flowline is blinded after meter building.

Pig barrel inspected.

Associated pipeline well vegetated.

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100037353  
Well ID: 16119  
Well Name: OVV ECOG HZ BRASSEY C- 039-B/093-P-10  
Location: NTS: C- 039-B/093-P-10

Permit: 100037353  
Facility ID: 00020174  
Facility Name: OVV DEEPBASIN C-039-B/093-P-10 001  
Facility Type: Well Facility  
Location: NTS: C- 039-B/093-P-10

---

Authorized by BCER