

## Inspection Report

Permit Holder: Ovintiv Canada ULC  
Inspection: 2026-1692  
Inspection Date: 2026-05-22  
Inspection Outcome: Inspected

### Inspection Comment:

Access and access signage inspected.

Pad clean.

Inspect wells. No SCV flow observed. Barricades present. Critical valves locked out. Meter building inspected.

Pig barrel inspected.

Chem tanks inspected.

Associated pipeline well vegetated.

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100061495  
Well ID: 23193  
Well Name: OVV HZ SUNDOWN B- 037-A/093-P-10  
Location: NTS: B- 037-A/093-P-10

Permit: 100077334  
Well ID: 28871  
Well Name: OVV CRP HZ SUNDOWN B-A037-A/093-P-10  
Location: NTS: B-A037-A/093-P-10

Permit: 100061495  
Facility ID: 00022995  
Facility Name: OVV DEEPBASIN B-037-A/093-P-10 001  
Facility Type: Well Facility  
Location: NTS: B- 037-A/093-P-10

Permit: 100077334  
Facility ID: 00025828  
Facility Name: OVV DEEPBASIN B-037-A/093-P-10 003  
Facility Type: Well Facility  
Location: NTS: B- 037-A/093-P-10



Inspection Number: 2026-1692  
Inspection Date: 2026-05-22

Letter ID: L2602400  
Letter Date: 2026-05-26

---

Authorized by BCER