

## Inspection Report

Permit Holder: PETRONAS Energy Canada Ltd.  
Inspection: 2026-1698  
Inspection Date: 2026-05-21  
Inspection Outcome: Inspected

### Inspection Comment:

This is a single well pad that only has a well head, a meter suitcase, a 1 pipe riser and a chemical tank. All have been suspended/deactivated. No concerns were noted at the time of the inspection

There is a bridge on the main access that is permitted to Petronas (road permit # 3692 segment #1). This bridge is just before the b-100-A well pad. As required under Section 14 of the Energy Resource Road Regulation, please submit your last annual and 3rd year bridge inspections to the inspector by the end of the day on June 16th 2026, Thank you.

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100058366  
Well ID: 22487  
Well Name: PETRONAS ALTARES B- 100-A/094-B-08  
Location: NTS: B- 100-A/094-B-08

Permit: 100058366  
Facility ID: 00022688  
Facility Name: PETRONAS ALTARES B-100-A/094-B-08 001  
Facility Type: Well Facility  
Location: NTS: B- 100-A/094-B-08

Permit: 100083330  
Road Number: 03692  
Segment IDs (Location): 001 (From NTS: C- 099-A/094-B-08 To NTS: A- 080-A/094-B-08)

---

Authorized by BCER