

Inspection Report

Permit Holder: PETRONAS Energy Canada Ltd.
Inspection: 2026-1699
Inspection Date: 2026-05-21
Inspection Outcome: Inspected

Inspection Comment:

This is a single well pad where the wellhead and facility are suspended, the pipeline deactivated and the chemical tank is empty. There is a yellow "lease operations" sign that is on the ground and needs to be removed. It is located approximately 200 from the beginning of the access on the left side of the road and amongst the alders. Please contact the inspector upon removal of the sign. Otherwise no concerns noted at the time of inspection.

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100058600
Well ID: 22600
Well Name: PETRONAS ALTARES D- 081-B/094-B-08
Location: NTS: D- 081-B/094-B-08

Permit: 100058600
Facility ID: 00022729
Facility Name: PETRONAS ALTARES D-081-B/094-B-08 001
Facility Type: Well Facility
Location: NTS: D- 081-B/094-B-08

Authorized by BCER