

Inspection Report

Permit Holder: PETRONAS Energy Canada Ltd.
Inspection: 2026-1700
Inspection Date: 2026-05-21
Inspection Outcome: Non-Compliance(s) Found

Inspection Comment:

This single well pad with the wellhead and facility are suspended and the pipeline deactivated. The chemical tank is empty. No concerns on the well pad.

An Inspection was conducted and as a result Non-Compliance(s) were found and must be corrected. For specifics on the Non-Compliances, refer to the **Non-Compliance Notice**.

To respond to these Non-Compliances, access the CM-IS Permit Holder Application.

Consideration should be given to checking your other locations for similar Non-Compliances.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100055865
Well ID: 21639
Well Name: PETRONAS ALTARES A- 010-H/094-B-08
Location: NTS: A- 010-H/094-B-08

Permit: 100055865
Facility ID: 00022319
Facility Name: PETRONAS BEG A-010-H/094-B-08 001
Facility Type: Well Facility
Location: NTS: A- 010-H/094-B-08

Permit: 100083013
Road Number: 03552
Segment IDs (Location): 001 (From NTS: A- 010-H/094-B-08 To NTS: C- 099-A/094-B-08)

Authorized by BCER