

Inspection Report

Permit Holder: PETRONAS Energy Canada Ltd.
Inspection: 2026-1701
Inspection Date: 2026-05-25
Inspection Outcome: Non-Compliance(s) Found

Inspection Comment:

All 3 wells Active.

Signs compliant.

Surface casing vents at c-A49-J and c-B49-J checked and compliant.

Burst plate installed on SCVA at c-49-J has ruptured in the recent past, creating an excavation in the dirt directly below the SCVA adjacent to the wellhead. Gas detector overranged on LEL, and H2S detected from the surface casing vent. The Company advises the well is currently being re-evaluated with a view to installing a replacement burst plate. See photos in the Gallery tab.

All well buildings compliant and critical valves secured.

Last instrumentation September 2025. Last meter cal/orifice plate inspection August 2024.

Chem tank and pig barrel compliant.

An Inspection was conducted and as a result Non-Compliance(s) were found and must be corrected. For specifics on the Non-Compliances, refer to the **Non-Compliance Notice**.

To respond to these Non-Compliances, access the CM-IS Permit Holder Application.

Consideration should be given to checking your other locations for similar Non-Compliances.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100078130
Well ID: 29223
Well Name: PETRONAS HZ CARIBOU C- 049-J/094-G-07
Location: NTS: C- 049-J/094-G-07

Permit: 100078388
Well ID: 29400
Well Name: PETRONAS HZ CARIBOU C-A049-J/094-G-07
Location: NTS: C-A049-J/094-G-07

Permit: 100078389
Well ID: 29401
Well Name: PETRONAS HZ CARIBOU C-B049-J/094-G-07
Location: NTS: C-B049-J/094-G-07

Permit: 100078130
Facility ID: 00017860
Facility Name: PETRONAS CARIBOU C-049-J/094-G-07 001
Facility Type: Well Facility
Location: NTS: C- 049-J/094-G-07

Authorized by BCER