

Inspection Report

Permit Holder: Whitecap Resources Inc.
Inspection: 2026-1705
Inspection Date: 2026-05-22
Inspection Outcome: Non-Compliance(s) Found

Inspection Comment:

COMMENTS:

- active electric pumpjack. No SCVF
- no visible location signage anywhere
- lease, access and signage are compliant.

An Inspection was conducted and as a result Non-Compliance(s) were found and must be corrected. For specifics on the Non-Compliances, refer to the **Non-Compliance Notice**.

To respond to these Non-Compliances, access the CM-IS Permit Holder Application.

Consideration should be given to checking your other locations for similar Non-Compliances.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100003816
Well ID: 02865
Well Name: WHITECAP ET AL BOUNDARY 07-02-085-14
Location: DLS: 07-02-085-14

Authorized by BCER