

## Inspection Report

Permit Holder: Canlin Energy Corporation  
Inspection: 2026-1707  
Inspection Date: 2026-05-22  
Inspection Outcome: Inspected

### Inspection Comment:

#### COMMENTS:

- active gas well. Barbed wire fencing around equipment. No SCVF
- lease and signage are compliant.
- the access road has some rutting due to spring run-off. The landowner mentioned that they would like the road to be fixed up a bit. Grader maybe?

A satisfactory inspection was conducted.

The following were the only items that were inspected during this inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this inspection.

Permit: 100005656  
Well ID: 03991  
Well Name: CANLIN ET AL BOUNDARY 09-09-085-14  
Location: DLS: 09-09-085-14

---

Authorized by BCER