

Inspection Report

Permit Holder: Whitecap Resources Inc.
Inspection: 2026-1708
Inspection Date: 2026-05-22
Inspection Outcome: Inspected

Inspection Comment:**COMMENTS:**

-wellhead only, valves chained and locked. Guarding around wellhead. No SCVF.
Location signage on wellhead.

A satisfactory inspection was conducted.

The following were the only items that were inspected during this inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this inspection.

Permit: 100024980
Well ID: 11416
Well Name: WHITECAP BOUNDARY 08-09-085-14
Location: DLS: 08-09-085-14

Authorized by BCER