

Inspection Report

Permit Holder: Canlin Energy Corporation
Inspection: 2026-1709
Inspection Date: 2026-05-22
Inspection Outcome: Inspected

Inspection Comment:**COMMENTS:**

- active gas well. Guarding around all equipment. No SCVF
- lease, access and signage are compliant.

A satisfactory Inspection was conducted.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100014359
Well ID: 08145
Well Name: CANLIN ET AL BOUNDARY 10-10-085-14
Location: DLS: 10-10-085-14

Permit: 100014359
Facility ID: 00019093
Facility Name: CANLIN BOUNDARYLAKE 10-10-085-14 001
Facility Type: Well Facility
Location: DLS: 10-10-085-14

Authorized by BCER