

Inspection Report

Permit Holder: Canadian Natural Resources Limited
Inspection: 2026-1729
Inspection Date: 2026-05-27
Inspection Outcome: Non-Compliance(s) Found

Inspection Comment:

Risk & Data Informed inspection of surface equipment on site.

Performed inspection of location at 1450HRS.

Access road- Vegetation growing on access road. No concerns at the time of inspection.

Lease environment- Moderate vegetation on lease. No erosion sediment or water runoff concerns.

Lease Equipment: Wellhead appears suspended but is an observation well according to internal records. Barricades in place. Signage in place. Positive isolation maintained (flow lines removed). Valve Handles chained, locked and secure.

Surface casing vent flow test- No Flow detected from glove test.

An Inspection was conducted and as a result Non-Compliance(s) were found and must be corrected. For specifics on the Non-Compliances, refer to the **Non-Compliance Notice**.

To respond to these Non-Compliances, access the CM-IS Permit Holder Application.

Consideration should be given to checking your other locations for similar Non-Compliances.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100009491
Well ID: 06482
Well Name: CNRL ET AL W STODDART 10-34-085-20
Location: DLS: 10-34-085-20

Permit: 100009491
Facility ID: 00018927
Facility Name: CNRL STODDARTWEST 10-34-085-20 001
Facility Type: Well Facility
Location: DLS: 10-34-085-20

Authorized by BCER



Inspection Number: 2026-1729
Inspection Date: 2026-05-27

Letter ID: L2602442
Letter Date: 2026-05-29