

## Inspection Report

Permit Holder: Pavilion Energy Corp.  
Inspection: 2026-1730  
Inspection Date: 2026-05-27  
Inspection Outcome: Non-Compliance(s) Found

### Inspection Comment:

Risk & Data Informed inspection of surface equipment on site.

Performed inspection of location at 1510HRS.

Access road- Road has deep ruts from water runoff and tire tracks (See attached).

Lease environment- Limited vegetation on lease.

Lease Equipment: Pumpjack active. No barricades in place (Limited risk due to isolated location). Signage in place. Surface casing vent flow test- No Flow detected from glove test. Various fittings on wellhead have greasy fluid, or crystallization around connections (See attached). Building entry test- No alarms on personal monitor. O2 detected on personal monitor upon entry of building- No alarms on personal monitor. Building window and doors have been removed.

Note: Ladder on pumpjack is vibrating creating a loud rattling.

An Inspection was conducted and as a result Non-Compliance(s) were found and must be corrected. For specifics on the Non-Compliances, refer to the **Non-Compliance Notice**.

To respond to these Non-Compliances, access the CM-IS Permit Holder Application.

Consideration should be given to checking your other locations for similar Non-Compliances.

The following were the only items that were inspected during this Inspection and does not absolve the company of Non-Compliances which may not have been observed, nor any Non-Compliances which occur subsequent to this Inspection.

Permit: 100006358  
Well ID: 04461  
Well Name: PAVILION W STODDART 06-35-085-20  
Location: DLS: 06-35-085-20

---

Authorized by BCER



Inspection Number: 2026-1730  
Inspection Date: 2026-05-27

Letter ID: L2602443  
Letter Date: 2026-05-29